
Hitachi HM55B Compass Module



www.parallax.com support@parallax.com

Out of the box

Description: The Hitachi HM55B Compass Module is a low cost, dual axis magnetic field sensor that can give your next electronic or robotic project a sense of direction. It is capable of detecting microtesla (μT) variations in magnetic field strength. North/south and east/west sensing axes make it easy for the BASIC Stamp® microcontroller to resolve and display direction in a 360° format, with magnetic north at 0°, northeast at 45°, east at 90°, south at 180°, and so on.



A sense of direction opens up a variety of BASIC Stamp project and product possibilities. Here are just a few examples:

- Mobile robot direction sensor
- · Weathervane indicator for remote weather stations
- Audible compass for the vision impaired
- Handheld electronic compass
- Automotive electronic compass

While this package insert provides an example circuit and test program, there are lots more online resources listed in the *Additional Resources* section.

Features:


- · Compact and breadboard-friendly package
- Easy to control and read with SHIFTOUT and SHIFTIN
- Sensitive to microtesla (μT) variations in magnetic fields
- · Dual axes simplifies direction determination
- Built-in resistor protection for data pins
- 6-Bit (64-direction) or better resolution after calibration
- Only 30 to 40 ms between start measurement and data-ready

Getting Started: Build the circuit on your BASIC Stamp carrier board from the schematic shown below. Either hand enter the example program (see other side) into your BASIC Stamp Editor, or open it after downloading it from the product page listed in *Additional Resources*. Run the program and verify that the compass module gives you an angle measurement that corresponds to the direction it is pointing. If you are comparing the compass module's readings to a magnetic compass, use the magnetic compass to align a non-metallic object to the direction you want to test. Then, set the magnetic compass well away from the object before testing the compass module against it.

For Best Results: Go to the Hitachi HM55B Compass Module product page, and download the *Hitachi HM55B Compass Module Documentation.pdf*. Operate on flat surface, away from magnetic field disturbances such as large metal objects, motors, coils, magnets, power cords and programming cables.

Precautions: Do not operate or store near strong magnetic fields created by bar magnets, electromagnets, or electric motors.

Schematic



Additional Resources

Check out the Hitachi HM55B Compass Module product page for complete product documentation, example programs, the Hitachi® HM55B datasheet, and more:

http://www.parallax.com/detail.asp?product_id=29123



Example BASIC Stamp Source Code

```
' ----[ Title ]-----
' TestHm55bCompass.bs2 - This Hitachi HM55B Compass Module test program displays x (N/S)
' and y (W/E) axis measurements along with the direction the Compass Module is pointing,
' measured in degrees clockwise from north.
' Author.... (C) 2005 Parallax, Inc -- All Rights Reserved
 Email..... support@parallax.com
' {$STAMP BS2}
' {$PBASIC 2.5}
' ----[ Pins/Constants/Variables ]-----
                                                 ' P6 tranceives to/from Din/Dout
DinDout PIN 6
Clk
             PIN
                                                 ' P5 sends pulses to HM55B's Clk
                                                 ' P4 controls HM55B's /EN(ABLE)
En
             PTN
                     %0000
Reset
                                                 ' Reset command for HM55B
            CON
Reset CON
Measure CON
Report CON
Ready CON
NegMask CON
                                                 ' Start measurement command
                     %1100
                                                 ' Get status/axis values command
                       %1100
                                                 ' 11 -> Done, 00 -> no errors
                                                 ' For 11-bit negative to 16-bits
                     %1111100000000000
                   Word
Word
            VAR
                                                 ' x-axis data
                                                 ' y-axis data
            VAR
status
                                                 ' Status flags
             VAR
                       Nib
                                                ' Store angle measurement
angle
             VAR
                       Word
' ----[ Main Routine ]-----
                                                ' Main loop
                                                 ' Get x, and y values
  GOSUB Compass Get Axes
  angle = x ATN - y
                                                 ' Convert x and y to brads
  angle = angle */ 360
                                                 ' Convert brads to degrees
  DEBUG HOME,
                                                 ' Display axes and degrees
     "x-axis N(-S) = ", SDEC x,
     CLREOL, CR, "y-axis W(-E) = ",
     SDEC y, CLREOL, CR, CR, "angle = ",
     DEC angle, " Degrees", CLREOL
  PAUSE 150
                                                 ' Debug delay for slower PCs
LOOP
                                                 ' Repeat main loop
' ----[ Subroutines ]-----
                                                 ' Compass module subroutine
Compass Get Axes:
                                                 ' Send reset command to HM55B
  HIGH En: LOW En
  SHIFTOUT DinDout, clk, MSBFIRST, [Reset\4]
  HIGH En: LOW En
                                                 ' HM55B start measurement command
  SHIFTOUT DinDout, clk, MSBFIRST, [Measure\4]
  status = 0
                                                 ' Clear previous status flags
                                                 ' Status flag checking loop
                                                 ' Measurement status command
     HIGH En: LOW En
     SHIFTOUT DinDout, clk, MSBFIRST, [Report\4]
     SHIFTIN DinDout, clk, MSBPOST, [Status\4]
                                                 ' Get Status
                                                 ' Exit loop when status is ready
  LOOP UNTIL status = Ready
                                                 ' Get x & y axis values
  SHIFTIN DinDout, clk, MSBPOST, [x\11, y\11]
                                                 ' Disable module
  HIGH En
  IF (y.BIT10 = 1) THEN y = y \mid NegMask IF (x.BIT10 = 1) THEN x = x \mid NegMask
                                                 ' Store 11-bits as signed word
                                                 ' Repeat for other axis
RETURN
```

Hitachi is a registered trademark of Hitachi, Ltd. BASIC Stamp is a registered trademark of Parallax Inc.

#29123 doc. ver. 1.3 • 05/05